

# Operating instructions

**Universal milling machine  
UF7- Gearbox**



© KUNZMANN Maschinenbau GmbH  
Tullastraße 29-31  
D-75196 Remchingen-Nöttingen

Tel.: +49 (0) 7232 3674-0  
Fax: +49 (0) 7232 3674-74

Service-Hotline  
Tel.: +49 (0) 7232 3674-6250 Mechanik  
Tel.: +49 (0) 7232 3674-6260 Elektrik  
Fax: +49 (0) 7232 3674-6290  
E-Mail: [info@kunzmann-fraesmaschinen.de](mailto:info@kunzmann-fraesmaschinen.de)  
Internet: [www.kunzmann-fraesmaschinen.de](http://www.kunzmann-fraesmaschinen.de)

<b>Operational safety / Additional information</b> .....	1
Transport instructions .....	2
Foundation plan .....	3
Space requirements .....	4
Electrical installation .....	5
Control devices .....	6
Cleaning-Lubrication-Putting to work.....	7
Lubrication .....	8
Component identification and controls I .....	9
Component identification and controls II .....	10
Operating instructions (electrical) .....	11
Control panel .....	12
Position limit switch .....	13
Setting of milling spindle speeds .....	14
Adjusting of the table feeds .....	15
Guide values for milling speeds I .....	16
Guide values for milling speeds II.....	17
Diagram of the main drive .....	18
Feed drive schematic .....	19
Diagram of transverse travels.....	20
Horizontal spindle with drive .....	21
V-Belt tension of the main drive.....	22
Feed gearbox drive .....	23
Feed gearbox drive, longitudinal section I.....	24
Feed gearbox drive, longitudinal section II .....	25
Feed gearbox output.....	26
Vertical longitudinal section, angle drive unit.....	27
Angle bracket on the drive side.....	28
Adjusting transverse threaded spindle play.....	29
Vertical drive, angle drive unit.....	30
Open vertical adjustment spindle.....	31
Longitudinal section and drive.....	32
Cross section, milling table.....	33
Left-hand partial view of the milling table.....	34
Connection measurements for dividing attachments.....	35

Longitudinal cut through the milling head holder.....36

Drive and support of the vertical head.....37

Cross section through the quill travel.....38

Current flow diagram.....39

Power flow chart, control circuit.....40

Power flow chart, DC circuit.....41

Electrical component list I.....42

Electrical component list II.....43

Coolant supply unit I.....44

Coolant supply unit II.....45

Overarm position for horizontal milling.....46

Overarm position for vertical milling.....47

**KUNZMANN** milling machines can be initially operated by trained personnel. For CNC machines we recommend that initial operation is carried out by the **KUNZMANN** service team.

When operating and serving **KUNZMANN** milling machines only appropriately qualified people are to be used. Incorrect use can lead to risk of life and limb, as well as to the destruction of various parts of the machine.

Protective equipment attached to the machines according to the valid accident prevention regulations may not be modified or removed. If this protective equipment fails, the machine may only be used again once said equipment has been repaired.

In the event of a change in the location of the machine or electrical disturbances, contact the **KUNZMANN** service team or arrange for them to visit.

Service and maintenance work may only be carried out when the machine are described in the operating instructions.

Persons contracted with the operation and maintenance of the machine must have read and understood these operating instructions. In order to avoid injury all activities are to be carried out by one operator. If necessary, the machine operator should wear protective goggles and protective shoes.

The operating instructions consist of the following sections: machine, control system, electrical equipment, accessories and service.



**We accept no liability for damages caused by not observing the specifications in the instructions or by improper procedure**

When contacting the **KUNZMANN** service team please always stipulate the machine number.

### Here are few tips for operational safety, which are to be especially considered when MILLING.

- ⇒ Clamp work pieces tight to prevent them from being spun out.
- ⇒ Before starting work, check the tool is correctly fitted.
- ⇒ If no extra anti-spray chip protection is available, set up protection or interception walls to protect against flying chips.
- ⇒ Only remove chips with aids, e.g. paint brush, brush, not with bare hands.
- ⇒ Add coolant when the milling cutter is at a stand still.
- ⇒ Do not reach into the danger area of the running milling cutter.
- ⇒ Only carry out measurements on the work piece or tool changes when milling cutter is at stand still.
- ⇒ When changing tools, do not grip a stationary milling cutter with bare hands, but always use appropriate protection such as a cloth.
- ⇒ When jogging or “scratching” a tool, you often come near the running spindle during visual inspection. This is why you must wear a hair net or a suitable cap.

Depending on the operating mode, the risk of an accident is reduced by corresponding safety equipment, e.g. protective doors monitored with limit switches, key operated switches for selecting the setting mode or acknowledge button on the hand wheel etc.

The polycarbonate panes of the cab enclosure are to be exchanged after 7 years due to the reduced protection.

#### Intended use

The milling machine and processing centres of **KUNZMANN** GmbH enable a range of different metal cutting options, e.g. milling , drilling , tapping.

The materials commonly used in mechanical engineering should preferably be used, e.g. steel grey cast iron and aluminium.

Other material such as paper, graphite, minerals or magnesium cannot be processed or only with appropriate protective equipment.



**Attention: Important additional information**



**Mains connection:**

The machine is equipped with a controller in B6 - wiring and may not be connected to a FI-protective switch.



⇒ ***Danger by electrical impact !***



It is absolutely necessary to use a another protective measure after VDE0100 part 410 or IEC 364-5-54 (e.g.: overcurrent release - zero position)!!!

# Transportanleitung

Transport instructions

UF6 u.7


Blatt: 2

## Für den Transport erforderlich:

- 1 Stck. Rundstahl 30 $\phi$  600 lang
- 1 Transportseil zul. Belastung mind. 2000 kg

## Required for hauling:

- 1 Round steel bar,  $\text{Ø}30$ , 600 long
- 1 Hauling rope admissible load at least 2000kg





# Fundamentplan

Foundation plan

UF 6, UF 7

VF 6, VF 7

Blatt 3


Bedienungseite der Maschine

Operating side of the machine



Steinschraube M 16 x 200 n DIN 529

Stone bolt M16x200 DIN529



Beton  
Concrete

Erwin Rudolf Kunzmann Pforzheim - Nöttingen




# Die Abmessungen

(Platzbedarf)

Space requirements

UF 7

Blatt: 4



Erwin Rudolf Kunzmann Pforzheim - Nöttingen

Erection

In order to ensure that the machine functions properly it will be absolutely required to place it on a well cured foundation.

Machines set up without sufficient anchoring are usually subject to undesired vibrations caused by a variety of factors.

Align the machine with a liquid scale in longitudinal and transverse direction.

The anchoring bolts of the accurately aligned machine must be grouted with a cement-sand mixture ( at least 1:3 ). Also, a cement-sand mixture may be applied under the machine base. This, however, is not absolutely necessary.

Mains connection ( Most important )

The machine has been laid out in the factory for the operating voltage specified in the order.

The mains connection box is at the machine base. Use steel wire conduit for a cable of at least 5 x 2,5 sqmm.

The green-yellow protective conductor of the connection line must be connected with the appropriate terminal in the connection box.

The other terminals in the connection box are as follows: Mp-RST.

Control voltage and current supply for the magnetic clutches are made available across built-in transformers.

The primary connections and the secondary outlets of the transformer are protected by fuses.

The main motor and the feed motor are provided, at the corresponding contactors, with fuses to act as overload protection.

A special motor cutout protects the coolant pump against over-current. Therefore, the coolant pump has no fuses.

For further particulars kindly attend to the instructions hereafter.


# Schalgeräte im Elektroschaltkasten

Control devices inside the control box

UF7; UF8

VF 7

Blatt: 6



Bitte Anschlußspannung beachten!

Note the operating voltage!

Erläuterungen der Schaltergerätekurzzeichen siehe Blatt 42 u. 43

Explanation of the control unit codes vide page 42 and 43

r5 und k5 entfallen bei UF7

r5 and k5 do not exist for UF 7



TO WORK

Cleaning and lubrication

All exposed parts are coated with a rust inhibitor. Before starting the machine make sure to remove all rust inhibitor and to lubricate the entire machine in accordance with the individual instructions and the lubrication plan.

It is recommended to use a good machine oil with a viscosity of approx. 3 - 5 Engler at 50° C. For example: Voltol Gleitöl II or another equal product, unless the lubrication plan specifies otherwise.

The roller bearings are lubricated with gease. The manufacturer recommends SKF roller bearing grease (Wälzerol II). The user is free to use any other branch with equal properties.

RED - Grease nipples should be lubricated with oil only.

BLUE - Grease nipples are for grease lubrication only.

Putting to work

When putting the machine to work for the first time, one of the three slowest speeds should be selected at the speed selector to enable the operator to check the proper functioning of the bearings and of the gears.

It is not advisable to start the machine with full load.

The user is recommended to perform all control functions with the machine cautiously before it is put to full use.

Machines equipped with a cooling attachment have the coolant tank in the machine base.

It will be easy to fill the coolant tank after the front cover has been removed.

Start the pump only after the tank has been filled.

We also recommend to comply fully with the instructions issued by the coolant pump manufacturer.


It is advisably to study the instructions hereafter and to make all control operations on a training basis without having the machine actuated ( Main Switch OFF ). Also pay particular attention to the positions and purposes of the limit switches and cams.



# Hauptschmieranweisung

UF 7 u. 8

Blatt 8



Schmierstoffübersicht			
DIN Bezeichnung	Werks Bezeichnung	Zähigkeit	Kennzeichen
Lagerschmieröl BRU DIN 6543		6,9 E 50	○ rot
Wälzlagerfett B DIN 6562			△ blau
Getriebeöl		SAE 90	⊘

Schmiervorschrift			
Schmierhäufigkeit	Schmierstoffe Nr.	Schmierstoffmenge	Bemerkungen
täglich	1 - 7	3-4 Hübe der Schmierpresse	
wöchentlich	8	4-6 Hübe der Schmierpresse	
wöchentlich	9 u. 9.1	3-4 Hübe der Fettschmierpresse	
alle 6 Monate	10 - 11	4,5 u. Glasurmarke nachfüllen	
alle 6 Monate	12	mit Wälzlagerfett füllen	
alle 6 Monate	13	Öl erneuern	

Erwin Rudolf Kunzmann Pforzheim-Nöttingen

- 1 Inspection glass for 11
- 2 Inspection glass for 13
- 3 Inspection glass for 10
- 4 Lubricate daily
- 5 Lubricate weekly
- 6 Lubricate according instructions below

7 Summary of lubricants

DIN Description	Works description	Viscosity	Key Symbol
Bearing lubricating oil Bka DIN 6543		4.5° E50°C	red
Roller bearing grease B DIN 6562		SAE 90	blue

8 For oil change, vide page 18 and 21

9 Lubricating Instructions

Lubricating Frequency	No. of lubrication point	Quantity of lubricant	Remarks
daily	1 - 7	3 - 4 strokes of gun	
weekly	8	4 - 6 strokes of gun	
weekly	9 & 9.1	3 - 4 strokes of grease gun	
every 6 months	10 - 11	top up to oil level mark	
every 6 months	12	pack with roller bearing grease	
every 6 months	13	re-new oil content	



# Bezeichnungen u. Bedienungen I


Component identification and controls I

UF 7

02.12.2

Coolant supply Kühltischlauf

Counter stop clamp Gegenstoppeklammer



Swivelled vertical milling head  
Frähsopf / geschwenkt

Overarm bearing  
Spindle carrier

Feed motor  
Verschub / Einfahr motor

Milling table  
Frästisch schwenker

Hand longitudinal feed  
Langschieber / schwenker

Transverse movement manual  
Vertical slide clamping

cable for milling table  
Control panel

angle bracket  
Winkelklammer


Hand vertical feed  
top Schneffenschleife (Sonderzubehör)

Unterbau  
Base

Cleaning aperture for coolant tank I  
Reinigungsöffnung für Kühlmittelbehälter (Zubehör)

Coolant drain  
Kühlmittelablaufschleife

## Designations and Operations II





Designations and Operations II

1. Oil sight glass for spindle carrier gear
2. Combines vertical head counter stop
3. Horizontal milling spindle
4. Electrical box
5. switch for coolant
6. Switch for feed
7. Switch for milling spindle
8. Control lamp for Master switch
9. Master switch
10. Milling spindle preselector
11. Oil sight for gearbox
12. Switch lever for gearbox (Milling spindle)
13. Mains connection box
14. Base
15. Scala for vertical milling spindle
16. Vertical milling head (swivelled)
17. Counter stop bearing for support journal
18. Cutter arbor
19. Milling table
20. Longitudinal limit switch
21. Hand longitudinal feed
22. Hand traverse feed
23. Table feed gear
24. Switch lever for gearbox ( feed )
25. Control panel
26. Vertical threaded spindle
27. Front plate for coolant tank
28. Cleaning trap for coolant tank
29. Cable conduit

OPERATING INSTRUCTIONS

(electrical)

UF7  
page 11

1. Switch in main switch a1 to I, hereafter control lamp h1 must give light.
2. Adjust direction of rotation and number of revolutions for milling spindle motor on switch a 3.
3. When working with feed adjust thereafter also number of revolution of the feed motor on a 4 (I or II).
4. Cooling pump can be switched on, too, after pouring cooling liquid in both containers of the substruction.

All switchgears mentioned up to now are situated laterally on the switchgear box which is on the backside of the machine.

5. Milling spindle can be switched on, with switch b 8 on the control panel.
6. Adjusting of the desired feed- respectively rapid traverse direction on the multi directional feed control switch.
7. Press either button b 6 ( feed EIN ) or button b 7 ( rapid traverse EIN ) so that milling table moves in the desired direction, provided that feed gear has been switched on before.
8. In any position the feed, whether longitudinal or vertical can be stopped by pressing button b 2 or button b 1. The rapid traverse is only as long in operation as button b 7 will be pressed manually.
9. In order to discontinue certain feed movements automatically, each direction of travel is provided with suitable limit switches with adjustable and fixed cams. The fixed cams limit the maximum feed travel and must on no account be removed.



For limit switch and cam positions, vide page 13 of these operating instructions.

# Der Steuerpult

Control panel

UF7, VF7

Blatt: 12




Erwin Rudolf Kunzmann Pforzheim-Nöttingen

Position of the movement limit switch  
Anordnung der Wegeendschalter

UF 7, UF 8  
 VF 7  
 Blatt 13



**Achtung!** Fest montierte Maximalwegenschläge dürfen auf keinen Fall entfernt werden.  
 Bewegliche Nocken können jederzeit nach gewünschter Fräslänge eingestellt werden.



longitudinal movement  
Längsbewegungen


Bahn A zu b3  
 Bahn B zu b3/1

Nicht bei UF 7 vorhanden  
 no by UF 7



traverse movement  
Querbewegungen

Bahn C zu b5  
 Bahn D zu b5/1



vertical movement  
Senkrechtbewegungen

Bahn E zu b4  
 Bahn F zu b4/1




# Setting of milling spindle speeds Einstellungen der Frasspindeldrehzahlen

UF 6u.7

(Machines ohne sep. Vertikalkopftrieb)  
Machines w/o separate vertical head drive

Blatt 14

Shift in idle only




## Zur besonderen Beachtung:

1. Gewünschte Spindeldrehzahl an Wänscheibe A während des Betriebes oder im Stillstand vorwählen.
2. In Auslauf Hebel B in Pfeilrichtung anlegen, womit vorgew. Drehzahl geschaltet wird.
3. Hebel B gleich wieder in Betriebsstellung

(siehe oben) zurücklegen. Maschine einschalten. Note: 1. Set required spindle speed on selector disk A during operation or at standstill  
2. In idle shift lever B in arrow direction thereby actuating the preselected speed. 3. Return lever B to operating position

(see above) Start Machine.

## Speed diagram



Horizontal

Vorwählscheibe  
Umdr/min

Motorstufe I

A	30
B	43
C	65
D	100
E	144
F	212
G	302
H	431
J	637

Motorstufe II

A	61
B	87
C	129
D	200
E	280
F	424
G	604
H	862
J	1275

Vertikal

Vorwählscheibe  
Umdr/min

Motorstufe I

A	66
B	98
C	142
D	224
E	322
F	452
G	674
H	960
J	1420

Motorstufe II

A	132
B	196
C	284
D	448
E	644
F	904
G	1348
H	1920
J	2840

# Adjusting of the table feeds Einstellungen der Tischvorschübe

**UF7;VF7**

Blatt: 15

Vorschubschaltgetriebe im Lauf, jedoch nicht unter Last schaltbar  
Feed gearbox can be shifted while rotating, but not under load

Settings Einstellungen	Vorschübe in mm pro Minute Feeds in mm/min.								Eilgänge in mm/min.
Feed-Motor <small>Vorschub Motor i = n 1400 i = n 3300</small>	Hebelstellungen Lever positions								Rapid movement in mm/min Eilgang Eilgeschwindigkeit
Bewegungen Movements									

Worm gear ratio in feed gear-box  $i = 15,33$   
Schneckenübersetzung im Vorschubgetriebe  $i = 15,33$

Longitudinal LANGS	I	8.0	10.8	16.8	23.6	32.0	50.0	69.0	93.0	146.0	742
	II	16.0	21.6	33.6	47.2	64.0	100.0	138.0	185.0	292.0	
Vertical VERTIKAL	I	1.6	2.16	3.36	4.72	6.40	10	13.8	18.6	29.2	168.4
	II	3.2	4.32	6.72	9.44	12.80	20	27.6	37.2	58.4	

$i = 11,25$

Longitudinal LANGS	I	10.4	14.0	22.0	30.8	42.0	65.3	90.0	122.0	190.0	1000
	II	20.8	28.0	44.0	61.6	84.0	130.6	180.0	244.0	380.0	
Vertical VERTIKAL	I	2.08	2.80	4.40	6.16	8.4	13.06	18.0	24.4	38.0	200
	II	4.16	5.60	8.80	12.32	16.8	26.12	36.0	48.8	76.0	

$i = 8,60$  (Standardausrüstung)  
(Standard equipment)

Longitudinal LANGS	I	14.4	19.4	30.0	42.5	56.0	90.0	122.0	168.0	266.0	1300
	II	28.8	38.8	60.0	85.0	112.0	180.0	244.0	336.0	532.0	
Vertical VERTIKAL	I	2.88	3.88	6.00	8.50	11.20	18.0	24.4	33.6	53.2	260
	II	5.76	7.76	12.00	17.00	22.40	36.0	48.8	67.2	106.4	

$i = 6,83$

Longitudinal LANGS	I	18.0	24.45	38.0	53.2	73.0	113.5	156.0	212.0	332.0	1640
	II	36.0	48.9	76.0	106.4	146.0	227.0	312.0	424.0	664.0	
Vertical VERTIKAL	I	3.60	4.89	7.60	10.64	14.6	22.7	31.2	42.4	66.40	328
	II	7.20	9.78	15.20	21.28	29.2	45.4	62.4	84.8	132.80	

$i = 5,57$  Getriebe mit dieser Übersetzung nur im Auslauf schalten  
Gearbox with this ratio to be shifted only as speed

Longitudinal LANGS	I	22.0	29.6	46.0	65.4	90.0	139.0	190.0	286.0	400.0	2015
	II	44.0	59.2	92.0	130.8	180.0	276.0	380.0	512.0	800.0	
Vertical VERTIKAL	I	4.40	5.90	9.20	13.0	18.0	27.6	38.0	51.2	80.0	403
	II	8.80	11.80	18.40	26.0	36.0	55.2	76.0	102.4	160.0	

**Erwin Rudolf Kunzmann Pforzheim-Nöttingen**



# Richtwerte für Fräsgeschwindigkeiten I

UF 56.78

VF 5.6.2

Blatt: 16

Schnittgeschwindigkeit  $v$  in m/min Vorschubgeschwindigkeit  $s'$  in mm/min

Fräserart und zu zerspanender Werkstoff	Schlichten bis Frästiefe 1mm		Schruppen bis Frästiefe 5 mm	
	$v$	$s'$	$v$	$s'$
<b>Walzenfräser DIN 884</b> Fräsbreite bis 100 mm				
Stahl 90...100 kg/mm <sup>2</sup> Festigkeit	10...14	35...45	10...12	45...70
Stahl 70...80 kg/mm <sup>2</sup> Festigkeit	14...18	40...60	12...14	70...100
Stahl 50...70 kg/mm <sup>2</sup> Festigkeit	18...22	50...80	15...18	90...150
Guß Eisen bis 200 Brinellhärte	14...18	70...90	12...14	100...170
Leichtmetall	200...300	100...150	150...250	150...280
Messing	40...60	100...160	30...40	150...220
<b>Schaftfräser DIN 844/845</b> Fräsbreite bis 60 mm				
Stahl 90...100 kg/mm <sup>2</sup> Festigkeit	16...18	40...50	12...14	15...25
Stahl 70...80 kg/mm <sup>2</sup> Festigkeit	18...20	55...75	14...16	25...40
Stahl 50...70 kg/mm <sup>2</sup> Festigkeit	20...24	75...90	16...18	35...55
Guß Eisen bis 200 Brinellhärte	18...20	80...100	14...16	40...75
Leichtmetall	150...180	70...100	140...180	50...90
Messing	50...60	100...135	30...40	60...100
<b>Walzensteinfräser DIN 841 u. 883</b> Fräsbreite bis 100 mm				
Stahl 50...100 kg/mm <sup>2</sup> Festigkeit	12...14	30...40	10...12	40...60
Stahl 70...80 kg/mm <sup>2</sup> Festigkeit	16...18	40...60	12...14	70...90
Stahl 50...70 kg/mm <sup>2</sup> Festigkeit	20...22	50...75	16...18	90...120
Guß Eisen bis 200 Brinellhärte	16...18	70...90	12...15	100...150
Leichtmetall	200...300	90...135	150...220	140...280
Messing	40...60	80...155	30...40	150...250
Kunststoffe*	25...30	40...70	15...22	60...80
Kunststoffe (Fräser m. Hartm. Schneid.)	30...40	40...70	25...35	60...80

Richtwerte für die zul. Spanmenge in cm<sup>3</sup>/kw min

Werkstoffe	Zulässige Spanmenge
Legierte Stähle (vergütet)	8...10 cm <sup>3</sup> /kw min
Legierte Stähle (geglüht)	10...12 cm <sup>3</sup> /kw min
Unlegierte Stähle	12...15 cm <sup>3</sup> /kw min
Guß Eisen (mittelhart)	20...26 cm <sup>3</sup> /kw min
Messing und Rotguß	30...40 cm <sup>3</sup> /kw min
Leichtmetalle	40...60 cm <sup>3</sup> /kw min


Erwin Rudolf Kunzmann Pforzheim-Nöttingen

# Richtwerte für Fräsgeschwindigkeiten II

UF 5,6,7,8  
VF 5,6,7  
Blatt: 17

Schnittgeschwindigkeit v in m/min		Vorschubgeschwindigkeit s' in mm/min					
Fräserart (HSS) u.z. zersp. Werkstoff		Schichten bis a 1mm		Schruppen bis a 5mm			
Messerbreite DIN 1030 Fräsbreite + 130mm		v	s'	v	s'		
STAHL:	90 ... 100	15 ... 20	30 ... 60	15 ... 18	60 ... 75		
Festigkeit kg/mm <sup>2</sup>	70 ... 80	20 ... 25	40 ... 70	20 ... 25	70 ... 100		
	50 ... 70	25 ... 30	40 ... 80	18 ... 22	80 ... 120		
GUSSEISEN Brinellhärte HB bis 200 (Vorbearbeitung mit Hartmetall)		60 ... 80	100 ... 150	60 ... 70	100 ... 150		
LEICHTMETALL		200 ... 400	80 ... 150	200 ... 300	150 ... 200		
MESSING		50 ... 80	90 ... 150	40 ... 60	100 ... 200		
Schleifenfräser DIN 885 Fräsbreite + 20 mm		Fertigfräsen bis a 40 mm		Vorschruppen bis a 10 mm			
		v	s'	v	s'		
STAHL:	90 ... 100	10 ... 14	10 ... 20	10 ... 12	40 ... 60		
Festigkeit kg/mm <sup>2</sup>	70 ... 80	14 ... 18	15 ... 25	12 ... 14	70 ... 90		
	50 ... 70	18 ... 22	20 ... 45	16 ... 18	80 ... 120		
GUSSEISEN Brinellhärte HB bis 200 (Vorbearbeitung mit Hartmetall)		14 ... 18	25 ... 50	12 ... 14	100 ... 150		
LEICHTMETALL		200 ... 300	60 ... 120	150 ... 250	150 ... 300		
MESSING		40 ... 60	40 ... 75	30 ... 40	140 ... 200		
Werkstoffkreiszögen DIN 1038 Schnittbreite + 3mm		Schnitttiefe bis a 4 mm		Schnitttiefe bis a 8mm			
		v	s'	v	s'		
STAHL:	90 ... 100	25 ... 30	30 ... 40	20 ... 25	20 ... 30		
Festigkeit kg/mm <sup>2</sup>	70 ... 80	35 ... 40	45 ... 60	30 ... 35	35 ... 60		
	50 ... 70	45 ... 50	60 ... 75	40 ... 45	45 ... 60		
GUSSEISEN Brinellhärte HB bis 200		30 ... 40	60 ... 80	30 ... 35	45 ... 60		
LEICHTMETALL		300 ... 400	200 ... 300	300 ... 350	150 ... 200		
MESSING		300 ... 400	200 ... 300	300 ... 400	150 ... 200		
BRANDSTOFFE		200 ... 300	150 ... 200	150 ... 200	80 ... 100		
Richtwerte für Vorschübe in mm/Fräserzahn (FRÄSER HSS)		Walzenfräser		Stirnfräser		Schleifenfräser	
		Schruppen		Schruppen		Schruppen	
		Schichten		Schichten		Schichten	
		a = 0mm	a = 5mm	a = 1mm	a = 8mm	a = 5mm	a = 1mm
STAHL:	bis ... 60	0,22	0,26	0,10	0,25	0,30	0,12
Festigkeit kg/mm <sup>2</sup>	60 ... 90	0,20	0,24	0,08	0,22	0,27	0,10
	90 ... 110	0,17	0,22	0,05	0,20	0,24	0,08
	über 110	0,10	0,12	0,04	0,12	0,14	0,06
GUSSEISEN:	bis 100	0,22	0,30	0,08	0,25	0,34	0,10
Härte Brinell (HB)	über 100	0,18	0,20	0,06	0,19	0,20	0,08
MESSING		0,24	0,28	0,10	0,25	0,30	0,10
LEICHTMETALL		0,10	0,12	0,04	0,12	0,16	0,06
KUPFER		0,26	0,30	0,08	0,26	0,30	0,10






# Schema des Vorschubantriebes

UF 7, VF

Blatt 19

## Feed drive schematic

Table threaded spindle, 4 mm pitch / Hofheinz magnetic gear clutch  
 Tischgewindespindel / Hofheinz Magnet-Zahnkupplung



z = Nr. of teeth




# Horizontalfrässpindel mit Antrieb

Horizontal milling spindle and drive

UF6,7

Blatt: 21



Erwin Rudolf Kunzmann Pforzheim - Nöttingen



V-belt tension of the main drive

# Keilriemenspannung des Hauptantriebes

UF6; UF7  
VF6; VF7  
Blatt: 22


Belt tension can be furnished or request  
Subsequent installation respectively order possible all times

Riemenspannrolle kann auf Wunsch mitgeliefert werden.  
Nachträglicher Anbau bzw. Bestellung\_jederzeit möglich.

1 Set of V-belts  
1 Satz Keilriemen  
4 Stck. NP17x1175

Waste oil screw  
Ölablaßschraube

nur nach innen  
spannen  
stretch only inwards



Ortlinghaus gear drive  
Ortlinghausgetriebe-  
Abtrieb




# Antrieb des Vorschubgetriebes

Feed gearbox drive

UF 7

Blatt: 23




Erwin Rudolf Kunzmann Pforzheim - Nöttingen

# Vorschubgetriebe im Längsschnitt I

Feed gearbox, longitudinal section I

UF7u.8

Blatt: 24



Erwin Rudolf Kunzmann Pforzheim-Nöttingen




# Vorschubgetriebe im Längsschnitt II

Feed gearbox, longitudinal section II

UF 7u.8

Blatt:25




Erwin Rudolf Kunzmann Pforzheim-Nöttingen

# Abtrieb vom Vorschubgetriebe

Feed gearbox output

UF 7

Blatt: 26






# Vertikaler Längsschnitt Winkelkonsole

Vertical longitudinal section angle drive unit

UF 7

Blatt: 27




Erwin Rudolf Kunzmann Pforzheim-Nöttingen





The angle bracket on the drive side  
 Die Winkelkonsole auf der Antriebsseite

UF7; VF7

Blatt: 23










Open vertical adjustment spindle  
Die offene Höhengewindespindel

MF 5.6.78

DF 5.6.78


Blatt 312



Erwin Rudolf Kunzmann Pforzheim-Nöttingen

Längsschnitt u. Antrieb Frästisch  
 Longitudinal section and drive, milling table

UF7, UF8  
 VF7  
 Blatt 32




Erwin Rudolf Kunzmann Pforzheim-Nöttingen

# Querschnitt Frästisch

Cross section of the milling table

UF 7; VF 7

Blatt: 33



Beim Auswechseln d. Zuführung Deckel einschrauben supply unit take off cover

Frästischführung milling table guide

Gleichziehen durch Schraubriegel fest u. rechts. slide tracks: tighten with screw clamps tightly left and right




# Frästisch linke Teilansicht

Left side view of the milling table

UF5,6,7

VF5,6,7

Blatt: 34



$D = 24 \text{ mm}$   
 $d = 16 \text{ mm}$

Skalerring

1:1

IMA 1000 03 010 00/05/70


# Anschlußmaße des Frästisches für Teilapparate

Measurements of milling table for deviding attachments

UF5.6.7


VF5.6.7

Blatt: 35



Ansicht W

View W



Pitch of table spindle thread      table size

UF 5/VF 5

a	d <sub>h5</sub>	l	t	u <sub>h9</sub>	n <sup>H7</sup>	b	w	r	Steigung des Tischspindelgewindes	h	Tischgröße
44	24	46	26,5	6	12	200	30	30	Tr 26x4	55	200x760


UF 6/UF 7/VF 6/VF 7

a	d <sub>h5</sub>	l	t	u <sub>h9</sub>	n <sup>H7</sup>	b	w	r	Steigung des Tischspindelgewindes	h	Tischgröße
44	24	46	26,5	6	14	240	30	30	Tr. 26 x 4	70	240 x 860

Erwin Rudolf Kunzmann Pforzheim - Nöttingen

Longitudinal section through milling head holder assembly HF4UF567  
Längsschnitt durch Fräskopfhalter kombiniert

Blatt: 36




Erwin Rudolf Kunzmann Pforzheim-Nöttingen



Vertical head drive and bearings  
 Antrieb u. Lagerung des Vertikalkopfes


MF4UF 5-6-7

Blatt: 37



Querschnitt durch die Pinolenbewegung  
Cross section through quill travel

UF 587  
Blatt 38




Erwin Rudolf Kunzmann Pforzheim-Nöttingen





Anschluß Blatt 39



Gültig auch für VF7

(nach Grundschaltplan 670220)

neue Ausführung mit Klöckner-Möller-Schütze

Stromlaufplan - Steuerung

UF7  
Blatt 40

Erwin Rudolf Kunzmann Pforzheim-Nöttingen


DIL 0-47

DIL 00-52


DIL 00-47

DIL 00-47

DIL 00-47



Anschluss Blatt 38



Müllschleusenkontakt

Windrosenschalter 30

neue Ausführung mit Klöckner-Möller-Schütze

Gültig auch für VF 7

UF 7  
Blatt 47

Stromlaufplan - Gleichstromteil

Erwin Rudolf Kunzmann Pforzheim-Nöttingen

ELECTRICAL COMPONENT LIST I

UF 7  
Page 42

- a 1 Mains master switch
- a 2 Motor circuit breaker for coolant pump
- a 3 Pole changer switch (Dahlander switch) for main and milling motors
- a 4 Pole changer (Dahlander) switch for feed motor
- b 1 "All off" push button for milling spindle and feed
- b 2 "Off button for feed
- b 3 and 3/1 Precision cam operated limit switches for longitudinal movement
- b 4 and 4/1 Precision cam operated limit switches for vertical movement
- b 5<sup>c</sup> "On" button for feed
- b 7 "On" button for rapid movement (non-locking)
- b 8 "On" button for milling spindles (horizontal and vertical)
- b 9 Plug unit on milling table
- b 10 Multi directional feed selector switch
- c 1 Motor relay for direction of feed motor rotation (anti-clockwise)
- c 2 Motor relay for direction of feed motor rotation (clockwise)
- c 3 Motor relay for feed
- c 4 Motor relay for rapid movement
- c 5 Motor relay for milling spindle
- e 1 Fuses, 6 Amp, for transformer primary
- e 3 Fuses, 6 Amp, for feed motor
- e 4 Fuses, 15 Amp, for milling spindle motor
- e 6 Fuse for 24 V AC control ( transformer secondary I)
- e 8 Fuse for 24 V DC (magnetic clutch supply )
- e 9 Bimetallic relay as thermal circuit breaker for milling spindle motor
- e 11 and 12 Bimetallic relay as thermal circuit breaker for feed motor ( clockwise/anti-clockwise)
- h 1 Telltale lamp for mains master switch



## Electrical component list II

- k 1 MP capacitor for feed
- k 2 MP capacitor for rapid movement
- k 3 MP capacitor for longitudinal movement
- k 5
- m 1 Control and magnetic clutch supply transformer
- m 3 Coolant pump motor
- m 4 Feed motor
- m 5 Milling spindle motor
- n 1 Selenium rectifier for magnetic clutches
- r 1 Protective resistor for feed clutch
- r 2 Protective resistor for rapid movement clutch
- r 3 Protective resistor for longitudinal movement clutch
- r 4 Protective resistor for vertical movement clutch
- s 1 Electromagnetic disc clutch for feed
- s 2 Electromagnetic disc clutch for rapid movement
- s 3 Electromagnetic gear clutch for longitudinal movement
- s 4 Electromagnetic gear clutch for vertical movement
- u 1 Optional machine light with switch

Terminals 1 - 26 for control and magnetic clutches

Terminals 30.- 44 for power circuit ( output to motors )

Terminals RST Mp distributors for power circuit

# Kühlmitteleinrichtung I

Coolant supply unit I


MEAVP5.67

UF5.67B


Blatt 44

Spacing at coolant  
unit

Abstände am  
Kühlmitteleinrichtung



Brinkmann - Coolantpump  
Brinkmann Kühlmittelepumpe  
Type T25/90



Erwin Rudolf Kunzmann - Pforzheim-Nöttingen

# Kühlmitteleinrichtung II

Coolant supply unit II

Prüfung 55/7

UF 5.6.78

Blatt 45

pipe Rohr

Nozzle  
Düse

Rohrhalter mit  
Rändelschraube

pipe clamp with knurled  
screw

Frästisch

Wasserzufluß

water feed

rechter o. linker  
Tischabfluß  
Plastikschlauch

Rh or LH table drain  
with plastic hose

chip tray  
Spänsfangschale

strainer  
Sieb

water return  
Wasserablauf

Pumpe mit Wasserbehälter  
im Unterbau

pump with water tank in base


Erwin Rudolf Kunzmann Pforzheim-Nöttingen



# Gegenhalterstellung beim Horizontalfräsen


Overrun position for horizontal milling

A




Größte (normale) Ausladung zum Horizontalfräsen  
Max. standard projection for horizontal milling

B



Minimale Ausladung zum Horizontalfräsen, wenn Vertikal Kopf noch nicht läuft  
Minimum projection for horizontal milling if milling head is inoperative

C



innermost standard position of overcut if vertical head does not run  
innerste (normale) Stellung des Gegenhalters, wenn Vertikal Kopf nicht läuft

Counter stop positions for vertical milling  
 Gegenhalterstellung beim Vertikalfräsen

HFZUF 8-2

Blatt 42

